

## Exhibit 1

|       |    |          |                                |  |                            |                   |
|-------|----|----------|--------------------------------|--|----------------------------|-------------------|
| 11677 | CN | 11/23/04 | Notes                          | Handwritten notes by A. Hartholt of Pinchin Environmental re: affected areas of texture coat | 100 Oak Street Hampton, SC | Speights & Runyan |
| 11677 | CN | Undated  | Drawings                       | Floor plans of Parkdale indicating locations of asbestos-containing materials                | 100 Oak Street Hampton, SC | Speights & Runyan |
| 11677 | CN | 2/19/90  | Report                         | Bulk Sample Analysis by Chatfield Technical Consulting Limited                               | 100 Oak Street Hampton, SC | Speights & Runyan |
| 11677 | CN | 1/8/01   | Report                         | Bulk Sample Analysis by McMaster University Lab  | 100 Oak Street Hampton, SC | Speights & Runyan |
| 11677 | CN | 5/25/04  | Report                         | Bulk Sample Analysis by McMaster University Lab  | 100 Oak Street Hampton, SC | Speights & Runyan |
| 11677 | CN | Undated  | Chart (attached to claim form) | School Facilities Inventory System: Facility Area and Age Data                               | 100 Oak Street Hampton, SC | Speights & Runyan |